

	speed	power	config
45° turns	120-125		G <u>u</u> F <u>u</u>
60° turns	120-125		G <u>u</u> F <u>u</u>

Slow flight

turns 15°	65		G <u>d</u>
power off stall			G <u>d</u> F <u>u</u>
no sharp break			
power off stall			G <u>d</u> F <u>d</u>
sharp break			
falling leaves			G <u>d</u> F <u>u</u>
power on stall	70	20x20	G <u>d</u> F <u>u</u>

Spiral-level at 90 Gu Fu
 wait for 60° or 135 mph, recover by
 level wing, when slow to 50-60 push over

Power off stall recovery:
 release stick, full power
 pick up low wing w/rudder

Power on stall recovery:
 release stick, pick up low wing w/rudder
 - make sure ~~the~~ ball in center when enter
 - never use more than 20x20